



Analysis of Venture Global Semi Annual Monitoring Reports

In its first year of operations, Venture Global's Calcasieu Pass facility in Cameron Parish had over 2,000 permit violations. Instead of solving the operational problems causing these accidents, Venture Global is asking the Louisiana Department of Environmental Quality (LDEQ) for emissions increases to cover the violations.

The following analysis of these reports was conducted by John Alliare, Mr. Allaire lives next door to Venture Global's Calcasieu Pass (VGCP) facility. He worked as an environmental engineer for BP / Amoco for over 30 years.

On March 17, 2023 Venture Global Calcasieu Pass (VGCP) requested that the Louisiana Department of Environmental Quality grant a major modification to its current Air Permit #0560-00987-V-4. Venture Global is also requesting that the LDEQ grant air permits for an expansion of the Calcasieu Pass terminal and a terminal in Plaquemines Parish, Louisiana. Both of these plants are of similar design to the existing VGCP facility which has been in operation since January of 2022. Venture Global's permit application for its Plaquemines facility says that the facility would be "technologically identical" to VGCP.

VGCP Air Permit Compliance History: This information was obtained from the VGCP certified 2022 semi-annual Title V permit monitoring reports that were submitted to the LDEQ on March 30, 2023. VGCP recorded over 2,000 deviations from 17 separate emission sources at its facility. Each of these deviations represents a release of pollutants that exceeds the limits set in their air permit. Each of these exceedances can be considered a permit violation for enforcement purposes. These reports reveal numerous cases of specific pieces of equipment exceeding permit limits for multiple pollutants throughout the course of 2022. Additionally, as detailed in the reports by VGCP, many of these permit exceedances occurred over multiple consecutive days. In total, out of 343 days of operation last year the facility was in violation of their permit for 286 days, meaning they were only in compliance for 17% of their time in operation last year.

Examples as follows:

Emission Source EQT 0008 was out of compliance from January 22, 2022 until June 14, 2022 for carbon monoxide, volatile organic compounds, Hazardous Air Pollutants and Toxic Air Pollutants. Over this 143 day period Venture Global knew it was violating its permit limits but continued to operate.

Emission Source EQT 0007 was out of compliance for over 120 days in 2022 exceeding permit limits for VOCs, NOx, CO, sulfur dioxide, and particulate matter.



There were 15 additional emission sources that had multiple permit exceedances during 2022. There were 32 separate occurrences in 2022 when VGCP continued to operate for more than 10 consecutive days with an emission source operating out of compliance with its permit. VGCP reports detail that of the 343 days they were operating in 2022, they were out of compliance with their air permit 286 of those days. The 2022 violations averaged 168 violations a month for 2023. VGCP facility was in compliance with their air permit 17% of the days in 2022.

As an excuse for noncompliance VGCP's deviation report repeatedly states the following (pp. 1 of Revised 1st Semiannual Monitoring report dated 01/01-6/31/2022) : "As described in a letter dated February 5, 2022, the hot oil heaters are a designed solution for the facility and since initial startup, they have experienced unexpected outages beyond the control of CP. The outages were caused primarily (but not exclusively) by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which caused the hot oil heater to trip."

What Venture Global is stating is that it selected and approved this design for installation. The company installed said design. It was a bad choice of design but the company will continue to operate the equipment while knowingly exceeding permit limits. How is it "beyond the control of CP?" It could shut down and then reengineer and install equipment that would operate as permitted.

The fact is that in 2022, VGCP has continued to operate out of compliance so that it could ship 128 cargoes of liquified gas to the highest overseas bidders and maximize profits at the expense of Louisiana's air quality.

Permit modifications requested: VGCP is requesting the following major modifications to its air permit to release additional pollutants, These changes include:

- Permission to increase flaring hours from current permit of 60 hours per year to 500 hours per year. This is an 833% increase.
- Permission to increase overall air emissions of pollutants by 680,883 tons per year from 3.9 million tons per year to 4.6 million tons per year. This is a 17% increase in toxic, hazardous, teratogenic, mutagenic or carcinogenic pollutants.
- A 17% increase of carbon dioxide for a total of 4.6 million tons per year.
- A 132% increase of an additional 115.44 tons per year mixture of undefined volatile organic compounds, hazardous air pollutants and toxic air pollutants for a total release of 202.61 tons per year.

Venture Global Calcasieu Pass LNG:

1st Semiannual Monitoring Report Annotated Copy (01/01/-06/30/2022)

Annotations on pages 1, 6-11, 18
Original version can be found [here](#)

CALCASIEU PASS
TransCameron
PIPELINE

1001 19th Street North
Suite 1500
Arlington, Virginia 22209

☎ 202.759.6740
F 703.243.1813
www.ventureglobaling.com

March 30, 2023

Title V Program
Office of Environmental Compliance
Enforcement Division
P.O. Box 4312
Baton Rouge, LA 70821-4312

RECEIVED

MAR 31 2023

LDEQ/OEC
ENFORCEMENT DIVISION

ORIGINAL

RE: Revised 1st Half of Reporting Year 2022 Title V Semiannual Monitoring Report
Reporting Period: 01/01/2022 – 06/30/2022
Venture Global Calcasieu Pass, LLC and TransCameron Pipeline, LLC
Calcasieu Pass Project
Title V Permit Number: 0560-00987-V4
Agency Interest Number: 194203

Dear Sir or Madam,

Venture Global Calcasieu Pass, LLC and TransCameron Pipeline, LLC (Calcasieu Pass), a wholly owned subsidiary of Venture Global LNG, Inc., operates the natural gas liquefaction, storage, and export facilities at a liquefied natural gas terminal on the east side of the Calcasieu Ship Channel in Cameron Parish, Louisiana. The facility is currently authorized under Title V Permit Number 0560-00987-V4 and Prevention of Significant Deterioration (PSD) Permit Number PSD-LA-805(M-4) issued on July 1, 2021 by the Louisiana Department of Environmental Quality (LDEQ).

Calcasieu Pass timely submitted its Title V Semiannual Monitoring Report (Title V SAMR) for the 1st Half of Reporting Year 2022.¹ While preparing the 2nd Half of Reporting Year 2022 Title V SAMR, Calcasieu Pass discovered some of the deviations were incorrectly reported in the 1st Half of Reporting Year 2022 Title V SAMR. Subsequently, Calcasieu Pass conducted a detailed reevaluation of this time period.

Calcasieu Pass is submitting a revised Title V SAMR for the reporting period January 1, 2022 through June 30, 2022 to take the place of the previously submitted report for the same time period. As such, Calcasieu Pass submits herein the revised Title V Semiannual Monitoring Report for Title V Permit Number 0560-00987-V4 for the reporting period January 1, 2022 through June 30, 2022.

¹ Refer to EDMS Document ID 13605970.

2023 MAR 30 PM 4:36

LDEQ PROJECT

40

Every industrial facility with an air permit is required to release a Semiannual Monitoring report detailing each violation of their permit limits over the given time period. Reports for the first half of the year are due September 30, and on March 31 of the following year for the second half.

Venture Global is operating in Cameron Parish via numerous subsidiaries (11 known)

The prior version of this report noted 32 permit deviations, this one has 75.

The attached Title V SAMR removes some of the prior reported deviations as well as adds additional deviations. The deviations consist primarily of intermittent exceedances of maximum hourly emissions limits (pounds per hour). No exceedances of annual emission limits (tons per year) occurred for any permitted emission source. In addition, Calcasieu Pass complied with the underlying regulatory standard. As described in the attached Title V SAMR, Calcasieu Pass has taken measures to correct any deviations.

Should you have any questions or require additional information, please contact Balaji Ganesan at (419) 508-4623 or at bganesan@venturegloballng.com.

Sincerely,



Andy Vaughan
Vice President, Operations
Venture Global Calcasieu Pass, LLC &
TransCameron Pipeline, LLC

Attachment

Title V Semiannual Monitoring Report (01/01/2022 - 06/30/2022)



Louisiana DEQ Title V Semiannual Monitoring Form

(Facility Identification)

Applicable Reporting Period: 1/1/22 to 6/30/22
mm/dd/yy mm/dd/yy

Company and Facility Identification					
Permit Number	0560-00987-V4	Parish	CAMERON	Date Permit Issued	7/1/21
Company Name	VENTURE GLOBAL CALCASIEU PASS, LLC				
Facility Name	CALCASIEU PASS PROJECT			Agency Interest Number	194203
Mailing Address	516 Davis Road				
City	Cameron	State	LA	Zip Code	70631
Contact Person	Balaji Ganesan	Phone #	4195084623	Fax #	
Principal Facility Product/Business	LNG				

Certification of Truth, Accuracy, and Completeness			
I certify, based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete.			
Responsible Official (signature)			
Responsible Official (typed)	Andy Vaughan	Date	29-MAR-2023
Responsible Official Title	Vice President, Operations		

RECEIVED
MAR 31 2023
LDEQ/CEQ
ENFORCEMENT DIVISION



Louisiana DEQ Title V Semiannual Monitoring Form


Deviation Reporting		
Title V Permit Number: 0560-00987-V4 Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC		
Facility Name: CALCASIEU PASS PROJECT AI Number: 194203		
Question	Response (Yes/No)	If the deviations have been previously reported, please reference below the report and date of the report.
Are there any instances of deviation from permit requirements being reported with this semiannual monitoring report? If yes, and they have not been previously reported, then complete the table entitled "Deviation Summary Report."	Yes	Unauthorized Discharge Written Report; Dated July 27, 2022 (EDMS Doc ID: 13462522). Unauthorized Discharge Written Report - OS1481; Dated January 24, 2022 (EDMS Doc ID 13136388)

* As with all Title V air permit application forms and compliance certifications, deviation reports must contain certification by a responsible official of truth, accuracy, and completeness. Also, any previous deviation reports must contain the information necessary to complete the "Deviation Summary Report" present. Therefore, if these two conditions are not satisfied, then the deviations inappropriately reported before must be appropriately reported in the "Deviation Summary Report."

Only two of seventy-five violations in this report were reported at the time of their occurrence to Louisiana Department of Environmental Quality

This column lists the piece of equipment that emissions are coming from

No indication that the underlying design problem is solved



Louisiana DEQ Title V Semiannual Monitoring Form

Title V Permit Number: 0560-00987-V4

Facility Name: CALCASIEU PASS PROJECT

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0006	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/15/22	2:00 PM	4/15/22	12:00 AM	5 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated NOx max. pounds per hour: 4.90 lb/hr - 4.95 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0006	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/15/22	9:00 AM	5/1/22	3:00 AM	65 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass since. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated CO max. pounds per hour: 10.44 lb/hr - 11.05 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0006	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/15/22	2:00 PM	5/1/22	3:00 AM	48 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated PM max. pounds per hour: 0.96 lb/hr - 1.0 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0006	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/15/22	2:00 PM	5/1/22	3:00 AM	58 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.72 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/16/22	8:00 PM	4/16/22	12:00 AM	4	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated NOx max. pounds per hour: 6.12 lb/hr - 6.32 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.

Page 1



Louisiana DEQ Title V Semiannual Monitoring Form

This same problem was responsible for
16 accidents in this report

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0007	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	2/26/22	5:00 PM	4/28/22	11:00 AM	87 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated CO max. pounds per hour: 10.44 lb/hr - 11.24 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/16/22	8:00 PM	4/28/22	6:00 AM	74 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated PM max. pounds per hour: 0.96 lb/hr - 1.02 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	4/16/22	8:00 PM	4/28/22	11:00 AM	81 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.74 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0008	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	3/1/22	12:00 PM	6/14/22	6:00 AM	29 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated NOx max. pounds per hour: 4.92 lb/hr - 6.76 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0008	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	1/22/22	6:00 PM	6/14/22	6:00 AM	212 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated CO max. pounds per hour: 10.44 lb/hr - 14.66 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL, CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0008	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	1/26/22	7:00 PM	6/14/22	6:00 AM	175 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated PM max. pounds per hour: 0.96 lb/hr - 1.33 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0008	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	1/22/22	6:00 PM	6/14/22	6:00 AM	202 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.96 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	3/19/22	9:00 PM	4/16/22	9:00 AM	60 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated NOx max. pounds per hour: 4.85 lb/hr - 5.35 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	3/19/22	9:00 PM	5/1/22	3:00 AM	211 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated CO max. pounds per hour: 10.44 lb/hr - 12.01 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	3/19/22	9:00 PM	5/1/22	3:00 AM	177 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated PM max. pounds per hour: 0.96 lb/hr - 1.09 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.

Instead of correcting the problem, they are asking to increase their permit limits.



Louisiana DEQ Title V Semiannual Monitoring Form

Emissions are likely far higher, since Venture Global assumes a high combustion rate

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0009	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	3/19/22	9:00 PM	5/1/22	4:00 AM	203 (intermittently)	As described in a letter dated February 5, 2022 (EDMS Document ID 13167131), the hot oil heaters are a custom designed solution for the facility and, since initial startup, they have experienced unexpected outages beyond the control of Calcasieu Pass. The outages were caused primarily by a design issue associated with the furnace assembly whereby heated flue gas was misdirected onto several heater instruments, resulting in the instruments overheating which then caused the hot oil heater to trip. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.79 lb/hr	Calcasieu Pass worked with the manufacturer of the hot oil heaters to replace parts and implemented mitigation measures to reduce the emissions. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0006	SO ₂	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	5/18/22	12:00 AM	6/30/22	12:00 AM	348 (intermittently)	Presence of dimethyl sulfide odorant in the pipeline feed gas	The deviations were previously reported, as described in the Unauthorized Discharge Written Report dated July 27, 2022 (EDMS Document ID 13462522). Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Major Modification of the PSD Permit No. PSD-LA-805(M-4) to update the maximum hourly emission rate.
EQT 0007	SO ₂	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	5/18/22	12:00 AM	6/30/22	12:00 AM	203 (intermittently)	Presence of dimethyl sulfide odorant in the pipeline feed gas	The deviations were previously reported, as described in the Unauthorized Discharge Written Report dated July 27, 2022 (EDMS Document ID 13462522). Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Major Modification of the PSD Permit No. PSD-LA-805(M-4) to update the maximum hourly emission rate.
EQT 0008	SO ₂	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	5/18/22	12:00 AM	6/30/22	12:00 AM	158 (intermittently)	Presence of dimethyl sulfide odorant in the pipeline feed gas	The deviations were previously reported, as described in the Unauthorized Discharge Written Report dated July 27, 2022 (EDMS Document ID 13462522). Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Major Modification of the PSD Permit No. PSD-LA-805(M-4) to update the maximum hourly emission rate.
EQT 0009	SO ₂	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	5/18/22	12:00 AM	6/30/22	12:00 AM	345 (intermittently)	Presence of dimethyl sulfide odorant in the pipeline feed gas	The deviations were previously reported, as described in the Unauthorized Discharge Written Report dated July 27, 2022 (EDMS Document ID 13462522). Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Major Modification of the PSD Permit No. PSD-LA-805(M-4) to update the maximum hourly emission rate.



Louisiana DEQ Title V Semiannual Monitoring Form

This same cut and paste explanation goes on for six pages.



Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/7/22	1:00 AM	3/7/22	2:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 176.96 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/7/22	8:00 PM	3/7/22	10:00 PM	2	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 182.37 lb/hr and 43.11 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/9/22	9:00 AM	3/9/22	10:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode, followed by a blackout. Estimated CO max. pounds per hour: 160.76 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/11/22	12:00 PM	3/11/22	3:00 PM	3	While commissioning the facility, an upset occurred, resulting in a load swing in SCCT1 (EQT 0034) causing the turbine to drop below MECL. Estimated NOx max. pounds per hour: 296.65 lb/hr, 296.65 lb/hr, and 123.18 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/15/22	11:00 AM	3/15/22	2:00 PM	3	While commissioning the facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 115.21 lb/hr, 151.44 lb/hr, and 94.19 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/20/22	11:00 PM	3/20/22	12:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 86.63 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/30/22	5:00 AM	3/30/22	7:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to instrumentation failure, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 151.48 lb/hr and 42.67 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/5/22	10:00 AM	4/5/22	12:00 PM	2	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 125.58 lb/hr and 44.65 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/9/22	12:00 AM	4/9/22	2:00 AM	2	While commissioning the liquefaction facility, an instrumentation failure resulted in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 64.4 lb/hr and 184.89 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/10/22	5:00 AM	4/10/22	7:00 AM	2	While commissioning the liquefaction facility, an upset occurred, resulting in a reduction in power and SCCT1 (EQT 0034) dropping below MECL. Estimated NOx max. pounds per hour: 53.32 lb/hr and 137.65 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/12/22	7:00 AM	4/12/22	9:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to a failed communication card which resulted in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 173.41 lb/hr and 42.8 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance and the faulty component was replaced. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/13/22	12:00 PM	4/13/22	1:00 PM	1	While commissioning the liquefaction facility, an upset occurred resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 55.74 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/22/22	6:00 PM	4/22/22	7:00 PM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 58.42 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	6/3/22	5:00 AM	6/3/22	6:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 42.17 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	6/29/22	10:00 AM	6/29/22	11:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 53.75 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	6/30/22	2:00 AM	6/30/22	3:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 64.69 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0034	VOC	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	3/22/22	12:00 PM	5/26/22	9:00 AM	76 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC 3-hour average: 2.01 lb/hr - 2.15 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of July 16, 2022, SCCT1 (EQT 0034) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0034	VOC and HAPs/TAPs	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/3/22	1:00 PM	5/26/22	9:00 AM	82 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC max. pounds per hour: 2.01 lb/hr - 2.24 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of July 16, 2022, SCCT1 (EQT 0034) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/18/22	3:00 AM	3/18/22	4:00 AM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 51.92 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/29/22	10:00 PM	3/29/22	12:00 PM	2	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 46.95 lb/hr and 115.98 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/30/22	1:00 PM	3/30/22	2:00 PM	1	While commissioning the liquefaction facility, an upset occurred due to instrumentation failure, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 76.53 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/5/22	10:00 AM	4/5/22	11:00 PM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 69.72 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/9/22	12:00 AM	4/9/22	2:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to instrumentation failure, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 70.07 lb/hr and 302.74 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/10/22	5:00 AM	4/10/22	8:00 PM	3	While commissioning the liquefaction facility, an upset occurred, resulting in a reduction in power and SCCT2 (EQT 0035) dropping below MECL. Estimated NOx max. pounds per hour: 117.91 lb/hr, 202.20 lb/hr, and 241.37 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/12/22	7:00 AM	4/12/22	9:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to a failed communication card, resulting in SCCT 2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 332.60 lb/hr and 94.02 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance and the faulty component was replaced. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/28/22	12:00 AM	4/28/22	1:00 AM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 55.43 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	5/9/22	9:00 AM	5/9/22	10:00 AM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 56.57 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	5/6/22	2:00 PM	5/6/22	3:00 PM	1	While commissioning the liquefaction facility, an upset occurred and tripped SCCT2 (EQT 0035). Estimated CO max. pounds per hour: 67.94 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	5/6/22	7:00 PM	5/6/22	8:00 PM	1	While commissioning the liquefaction facility, an upset occurred and tripped SCCT2 (EQT 0035). Estimated CO max. pounds per hour: 109.86 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	5/7/22	12:00 AM	5/7/22	2:00 AM	2	While commissioning the liquefaction facility, an upset occurred and tripped SCCT1 (EQT 0034), SCCT2 (EQT 0035), and SCCT3 (EQT 0036), followed by power outage (blackout). Estimated NOx max. pounds per hour: 164.48 lb/hr and 242.91 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0035	VOC	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	3/26/22	11:00 AM	5/26/22	9:00 AM	13 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC 3-hour average: 2.01 lb/hr - 2.04 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 6, 2022, SCCT2 (EQT 0035) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0035	VOC and HAPs/TAPs	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/26/22	10:00 AM	5/26/22	9:00 AM	21 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC max. pounds per hour: 2.01 lb/hr - 2.14 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 6, 2022, SCCT2 (EQT 0035) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0036	VOC	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	3/24/22	10:00 AM	4/29/22	12:00 PM	99 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC 3-hour average: 2.01 lb/hr - 2.21 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 29, 2022, SCCT3 (EQT 0036) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0036	VOC and HAPs/TAPs	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/24/22	9:00 AM	5/7/22	10:00 AM	100 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC max. pounds per hour: 2.01 lb/hr - 2.27 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 29, 2022, SCCT3 (EQT 0036) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/7/22	1:00 AM	3/7/22	3:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to an instrumentation trip, resulting in SCCT3 (EQT 0036) going into full speed no load (FSNL) operating mode. Estimated NOx max. pounds per hour: 51.3 lb/hr and 101.11 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/7/22	1:00 PM	3/7/22	3:00 PM	2	While commissioning the liquefaction facility, an upset occurred due to an instrumentation trip, resulting in SCCT3 (EQT 0036) going into full speed no load (FSNL) operating mode. Estimated NOx max. pounds per hour: 132.29 lb/hr and 173.96 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

This same cut and paste explanation goes on for three pages



Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/11/22	12:00 PM	3/11/22	3:00 PM	3	While commissioning the facility, an upset occurred due to an instrumentation trip, resulting in SCCT3 (EQT 0036) dropping below MECL. Estimated NOx max. pounds per hour: 326.83 lb/hr, 333.13 lb/hr, and 77.7 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/15/22	11:00 AM	3/15/22	12:00 PM	1	While commissioning the liquefaction facility, an upset occurred that caused SCCT2 (EQT 0035) to trip, resulting in SCCT3 (EQT 0036) going into full speed no load (FSNL) operating mode. Estimated NOx max. pounds per hour: 52.81 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/15/22	10:00 AM	3/15/22	12:00 PM	2	While commissioning the liquefaction facility, an upset occurred that caused SCCT2 (EQT 0035) to trip, resulting in SCCT3 (EQT 0036) going into full speed no load (FSNL) operating mode. Estimated CO max. pounds per hour: 55.34 lb/hr and 65.74 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/17/22	8:00 AM	3/17/22	9:00 AM	1	While commissioning the liquefaction facility, an upset occurred due to an equipment failure, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 194.24 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/18/22	3:00 AM	3/18/22	4:00 AM	1	While commissioning the liquefaction facility, a process unit tripped, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 116.56 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/22/22	12:00 AM	3/22/22	2:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to an instrumentation failure, resulting in SCCT3 (EQT 0036) dropping below MECL. Estimated NOx max. pounds per hour: 121.68 lb/hr and 136.49 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/22/22	9:00 AM	3/22/22	11:00 AM	2	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 167.15 lb/hr and 157.33 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/29/22	11:00 PM	3/29/22	12:00 AM	1	While commissioning the liquefaction facility, an instrumentation failure occurred, resulting in SCCT3 (EQT 0036) dropping below MECL. Estimated NOx max. pounds per hour: 181.88 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/3/22	3:00 PM	4/3/22	4:00 PM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT3 (EQT 0036) dropping below MECL. Estimated NOx max. pounds per hour: 148.90 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/4/22	8:00 AM	4/4/22	9:00 AM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 57.02 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/5/22	10:00 AM	4/5/22	12:00 PM	2	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean mode. Estimated NOx max. pounds per hour: 95.27 lb/hr and 103.57 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premiss operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/10/22	5:00 AM	4/10/22	8:00 AM	3	While commissioning the liquefaction facility, an upset occurred, resulting in a reduction in power and SCCT3 (EQT 0036) dropping below MECL. Estimated NOx max. pounds per hour: 116.58 lb/hr, 355.72 lb/hr, and 49.29 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premiss operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/12/22	7:00 AM	4/12/22	9:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to a failed communication card, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 291.42 lb/hr and 177.95 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance and the faulty component was replaced. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premiss operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	4/22/22	6:00 PM	4/22/22	7:00 PM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 58.29 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premiss operating mode.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	6/2/22	10:00 PM	6/2/22	11:00 PM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 124.43 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premiss operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	6/3/22	2:00 AM	6/3/22	3:00 AM	1	While commissioning the liquefaction facility, an upset occurred, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 128.77 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0051	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/10/22	6:00 AM	3/10/22	10:00 AM	4	After a cold startup, the ASCCT (EQT 0051) experienced an emissions exceedance. Estimated NOx max. pounds per hour: 4.39 lb/hr - 2.81 lb/hr	The proper operation of the control device (selective catalytic reduction) was verified, the aqueous ammonia injection components were inspected, and the power output (MW) was adjusted to return ASCCT (EQT 0051) to emissions compliance.
EQT 0051	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/12/22	8:00 AM	3/12/22	10:00 AM	2	Due to an equipment upset, the fuel gas operating temperature decreased, which changed the operating mode of ASCCT (EQT 0051). Estimated NOx max. pounds per hour: 8.98 lb/hr and 11.94 lb/hr	The fuel gas heater was reset and used to raise the fuel gas temperature, and ASCCT (EQT 0051) was returned to emissions compliance.
EQT 0051	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	3/13/22	10:00 AM	3/12/22	11:00 AM	1	Due to cold weather, an adjustment to the glycol system changed the operating mode of ASCCT (EQT 0051). Estimated NOx max. pounds per hour: 2.78 lb/hr	The glycol system was re-adjusted and ASCCT (EQT 0051) was returned to emissions compliance.

Venture Global Calcasieu Pass LNG:

**2nd Semiannual Monitoring Report Annotated Copy
(07/01-12/31/2022)**

Annotations on pages 2; 5-13
Original version can be found [here](#)

Venture Global is headquartered in Virginia


This report is due on March 31 every year

AKA - Venture Global

Not uploaded on LDEQ public database until April 28

Two of these reports must be submitted every year, on Sept. 30th and March 31st

This person is based in Houston



ATTACHMENT 1

Title V Semiannual Monitoring Report (07/01/2022 - 12/31/2022)



Louisiana DEQ Title V Semiannual Monitoring Form

(Facility Identification)

Applicable Reporting Period: 7/1/22 to 12/31/22
mm/dd/yy mm/dd/yy

Company and Facility Identification					
Permit Number	0560-00987-V4	Parish	CAMERON	Date Permit Issued	7/1/21
Company Name	VENTURE GLOBAL CALCASIEU PASS, LLC				
Facility Name	CALCASIEU PASS PROJECT			Agency Interest Number	194203
Mailing Address	516 Davis Road				
City	Cameron	State	LA	Zip Code	70631
Contact Person	Balaji Ganesan	Phone #	419-508-4623	Fax #	
Principal Facility Product/Business	LNG				

Certification of Truth, Accuracy, and Completeness			
I certify, based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete.			
Responsible Official (signature)			
Responsible Official (typed)	Andy Vaughan	Date	29-MAR-2023
Responsible Official Title	Vice President, Operations		

RECEIVED

MAR 31 2023

LDEQ/O&C
ENFORCEMENT DIVISION



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Reporting		
Title V Permit Number: 0560-00987-V4 Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC		
Facility Name: CALCASIEU PASS PROJECT AI Number: 194203		
Question	Response (Yes/No)	If the deviations have been previously reported, please reference below the report and date of the report.
Are there any instances of deviation from permit requirements being reported with this semiannual monitoring report? If yes, and they have not been previously reported, then complete the table entitled "Deviation Summary Report."	Yes	Unauthorized Discharge Written Report, Dated July 27, 2022 (EDMS Doc ID: 13462522)

* As with all Title V air permit application forms and compliance certifications, deviation reports must contain certification by a responsible official of truth, accuracy, and completeness. Also, any previous deviation reports must contain the information necessary to complete the "Deviation Summary Report" present. Therefore, if these two conditions are not satisfied, then the deviations inappropriately reported before must be appropriately reported in the "Deviation Summary Report."

Only one of sixty-four violations in this report were reported at the time of its occurrence to Louisiana Department of Environmental Quality



6 accidents on this page

Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0001	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/10/22	12:00 PM	11/10/22	2:00 PM	2	While commissioning the liquefaction facility, a liquefaction train tripped, resulting in CCCT1 (EQT 0001) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 147.71 lb/hr and 96.21 lb/hr	Operators performed a high load transfer of CCCT1 (EQT 0001) and restored the turbine into premix operating mode.
EQT 0001	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/16/22	12:00 PM	11/16/22	3:00 PM	3	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in CCCT1 (EQT 0001) tripping and dropping below MECL. Estimated NOx max. pounds per hour: 70.54 lb/hr, 74.72 lb/hr, and 95.72 lb/hr	Operators restored CCCT1 (EQT 0001) to MECL.
EQT 0001	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/17/22	9:00 AM	11/17/22	2:00 PM	5	An extended startup following a facility blackout resulted in CCCT1 (EQT 0001) dropping below MECL. Estimated NOx max. pounds per hour: 105.39 lb/hr - 257.24 lb/hr	Operators restored CCCT1 (EQT 0001) to MECL.
EQT 0001	NOx	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	11/17/22	9:00 AM	11/17/22	2:00 PM	5	An extended startup following a facility blackout resulted in CCCT1 (EQT 0001) dropping below MECL. Estimated 10-hr avg. NOx pounds per hour: 94.66 lb/hr	Operators restored CCCT1 (EQT 0001) to MECL.
EQT 0001	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/28/22	12:00 AM	12/28/22	1:00 AM	1	The black start of the facility after a freeze event resulted in CCCT1 (EQT 0001) dropping below MECL. Estimated NOx max. pounds per hour: 104.45 lb/hr	Operators restored CCCT1 (EQT 0001) to MECL.
EQT 0002	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/15/22	10:00 PM	11/16/22	10:00 AM	12	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in CCCT2 (EQT 0002) tripping and dropping below MECL. Estimated NOx max. pounds per hour: 27.48 lb/hr - 111.11 lb/hr	Operators restored CCCT2 (EQT 0002) to MECL.

What happened to the power source?

There are twelve pages of accidents in this report



Louisiana DEQ Title V Semiannual Monitoring Form

Cutting and pasting answers violates the intent of the law: to understand and correct the root cause of the problem

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0002	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/27/22	12:00 AM	12/28/22	1:00 AM	25	During the extreme weather conditions (freeze event), blackout, and the black start of the facility, CCCT2 (EQT 0002) tripped, resulting in the turbine dropping into extended lean-lean operating mode and experiencing instrumentation issues. Estimated NOx max. pounds per hour: 109.27 lb/hr - 333.87 lb/hr	Operators restored CCCT2 (EQT 0002) to MECL as soon as practical after the extreme weather event had passed and instrumentation issues were resolved.
EQT 0003	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/10/22	10:00 AM	11/10/22	2:00 PM	4	A process upset, resulting in CCCT3 (EQT 0003) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 28.06 lb/hr - 126.62 lb/hr	Operators restored CCCT3 (EQT 0003) to MECL.
EQT 0003	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/15/22	10:00 PM	11/16/22	5:00 AM	7	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in CCCT3 (EQT 0003) tripping and dropping below MECL. Estimated NOx max. pounds per hour: 49.17 lb/hr - 63.44 lb/hr	Operators restored CCCT3 (EQT 0003) to MECL.
EQT 0003	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/3/22	11:00 PM	12/4/22	1:00 AM	2	A process upset, resulting in CCCT3 (EQT 0003) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 40.63 lb/hr and 42.24 lb/hr	Operators restored CCCT3 (EQT 0003) to MECL.
EQT 0004	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/26/22	2:00 PM	8/26/22	6:00 PM	4	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in CCCT4 (EQT 0004) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 64.20 lb/hr - 79.91 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT4 (EQT 0004) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0004	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/2/22	12:00 AM	9/2/22	7:00 AM	7	The facility experienced a blackout, resulting in CCCT4 (EQT 0004) dropping below MECL. Estimated NOx max. pounds per hour: 52.89 lb/hr - 197.97 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT4 (EQT 0004) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0004	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/14/22	5:00 PM	9/14/22	6:00 PM	1	While commissioning the liquefaction facility, an upset occurred, resulting in CCCT4 (EQT 0004) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 125.41 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT4 (EQT 0004) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0004	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/15/22	10:00 PM	11/16/22	10:00 AM	11	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in CCCT4 (EQT 0004) tripping and dropping below MECL. Estimated NOx max. pounds per hour: 19.37 lb/hr - 138.82 lb/hr	Operators restored CCCT4 (EQT 0004) to MECL.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/24/22	3:00 AM	8/24/22	5:00 AM	2	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in CCCT5 (EQT 0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 32.15 lb/hr and 370.81 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT5 (EQT 0005) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.

Additional November accidents are listed on p.12

This 1 phrase is cut and pasted 25 times



Louisiana DEQ Title V Semiannual Monitoring Form

Why did they begin operations without an Energy Management System?

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/26/22	7:00 PM	8/26/22	9:00 PM	2	While commissioning the liquefaction facility, a liquefaction train tripped, resulting in CCCT5 (EQT 0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 87.92 lb/hr and 25.34 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT5 (EQT 0005) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/2/22	4:00 AM	9/2/22	7:00 AM	3	The facility experienced a blackout, resulting in CCCT5 (EQT 0005) dropping below MECL. Estimated NOx max. pounds per hour: 20.08 lb/hr - 51.25 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT5 (EQT 0005) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/14/22	5:00 PM	9/14/22	6:00 PM	1	While commissioning the liquefaction facility, an upset occurred due to equipment tripping, resulting in CCCT5 (EQT 0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 20.42 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and CCCT5 (EQT 0005) was returned to emissions compliance. The EMS became available in November 2022 and will minimize trips of the turbines and will ensure the turbines operate within MECL and within premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/10/22	8:00 PM	12/10/22	10:00 PM	2	Equipment malfunction, resulting in CCCT5 (EQT0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 57.75 lb/hr and 35.35 lb/hr	Operators performed a high load transfer of CCCT5 (EQT 0005) to restore the turbine into premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/15/22	6:00 AM	12/20/22	7:00 PM	5 (intermittently)	Equipment malfunction, resulting in CCCT5 (EQT0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 41.38 lb/hr - 74.01 lb/hr	Operators performed a high load transfer of CCCT5 (EQT 0005) to restore the turbine into premix operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/21/22	3:00 PM	12/21/22	10:00 PM	4 (intermittently)	A process upset occurred, resulting in CCCT5 (EQT0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 18.49 lb/hr - 187.11 lb/hr	Operators performed a high load transfer of CCCT5 (EQT 0005) to restore the turbine into premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/22/22	1:00 AM	12/22/22	5:00 AM	9 (intermittently)	A process upset occurred, resulting in CCCT5 (EQT0005) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 24.79 lb/hr - 187.11 lb/hr	Operators performed a high load transfer of CCCT5 (EQT 0005) to restore the turbine into premix operating mode.
EQT 0005	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/31/22	12:00 AM	12/31/22	2:00 PM	6 (intermittently)	During the extreme weather conditions (freeze event), blackout, and the black start of the facility, CCCT5 (EQT 0005) tripped, resulting in the turbine dropping into extended lean-lean operating mode and experiencing instrumentation issues. Estimated NOx max. pounds per hour: 29.9 lb/hr - 197.89 lb/hr	Operators performed a high load transfer of CCCT5 (EQT 0005) to restore the turbine into premix operating mode; however, the turbine tripped frequently and was shutdown completely.
EQT 0006	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/31/22	8:00 PM	11/22/22	10:00 AM	7 (intermittently)	Fuel flow rate higher than the current permit basis Estimated CO max. pounds per hour: 10.47 lb/hr - 10.76 lb/hr	Operators reduced fuel flow rate to restore HOH1 (EQT 0006) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0006	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/31/22	8:00 PM	11/22/22	10:00 AM	5 (intermittently)	Fuel flow rate higher than the current permit basis Estimated PM max. pounds per hour: 0.96 lb/hr - 0.97 lb/hr	Operators reduced fuel flow rate to restore HOH1 (EQT 0006) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.

Knowingly exceeding permits

Rather than solve the problem, they are asking for an emissions increase



Louisiana DEQ Title V Semiannual Monitoring Form

Two pages of the same
accident and explanation

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4				Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC								
Facility Name: CALCASIEU PASS PROJECT				AI Number: 194203								
Emission Source No/ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0006	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	8/31/22	8:00 PM	11/22/22	10:00 AM	7 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.70 lb/hr	Operators reduced fuel flow rate to restore HOH1 (EQT 0006) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/1/22	7:00 AM	9/7/22	6:00 AM	3 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated CO max. pounds per hour: 10.44 lb/hr - 10.57 lb/hr	Operators reduced fuel flow rate to restore HOH2 (EQT 0007) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/1/22	7:00 AM	9/1/22	8:00 AM	1	Fuel flow rate higher than the current permit basis. Estimated PM max. pounds per hour: 0.96 lb/hr	Operators reduced fuel flow rate to restore HOH2 (EQT 0007) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0007	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/1/22	7:00 AM	9/1/22	8:00 AM	1	Fuel flow rate higher than the current permit basis. Estimated VOC max. pounds per hour: 0.69 lb/hr	Operators reduced fuel flow rate to restore HOH2 (EQT 0007) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0008	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/7/22	4:00 AM	12/16/22	6:00 PM	36 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated CO max. pounds per hour: 10.44 lb/hr - 12.60 lb/hr	Operators reduced fuel flow rate to restore HOH3 (EQT 0008) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.



Emissions for all accidents are likely much higher as
Venture Global assumes a high combustion rate

Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report												
Title V Permit Number: 0560-00987-V4			Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC									
Facility Name: CALCASIEU PASS PROJECT			AI Number: 194203									
Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0008	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/20/22	8:00 AM	12/16/22	6:00 PM	26 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated PM max. pounds per hour: 0.96 lb/hr - 1.14 lb/hr	Operators reduced fuel flow rate to restore HOH3 (EQT 0008) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0008	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/7/22	8:00 AM	12/16/22	6:00 PM	32 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.92 lb/hr	Operators reduced fuel flow rate to restore HOH3 (EQT 0008) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	CO	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/5/22	9:00 AM	9/8/22	1:00 AM	40 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated CO max. pounds per hour: 10.44 lb/hr - 10.96 lb/hr	Operators reduced fuel flow rate to restore HOH4 (EQT 0009) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	PM	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/5/22	1:00 PM	9/7/22	10:00 AM	31 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated PM max. pounds per hour: 0.96 lb/hr - 0.99 lb/hr	Operators reduced fuel flow rate to restore HOH4 (EQT 0009) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.
EQT 0009	VOC and HAPs/TAPs	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	9/5/22	9:00 AM	9/7/22	11:00 AM	38 (intermittently)	Fuel flow rate higher than the current permit basis. Estimated VOC max. pounds per hour: 0.69 lb/hr - 0.72 lb/hr	Operators reduced fuel flow rate to restore HOH4 (EQT 0009) into emission compliance. Additionally, on March 17, 2023 (EDMS Document ID 13730261), Calcasieu Pass submitted an application for the Renewal and Significant Modification of the Title V Permit No. 0560-00987-V4 to update the maximum hourly emission rate.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0013 and EQT 0014	Visible Emissions	SRs 52 and 59	Design and operate for no visible emissions, as determined by the methods specified in 40 CFR 60.18(f), except for periods not to exceed a total of 5 minutes during any two consecutive hours. [40 CFR 60.18(c)(1)] Opacity <= 20 percent, except for emissions that have an average opacity in excess of 20 percent for not more than one six-minute period in any 60 consecutive minutes. [LAC 33:III.1311.C]	Review Method 9 Reports	Continuously	7/18/22	1:03 PM	7/18/22	2:42 PM	1.7	While commissioning the liquefaction facility, a power outage occurred, resulting in the flare blowers being inoperable, which resulted in visible emissions from the Warm Flare (EQT 0013) and Cold Flare (EQT 0014) which are air-assisted.	Power was restored to the flare blowers.
EQT 0013 and EQT 0014	Visible Emissions	SRs 52 and 59	Design and operate for no visible emissions, as determined by the methods specified in 40 CFR 60.18(f), except for periods not to exceed a total of 5 minutes during any two consecutive hours. [40 CFR 60.18(c)(1)] Opacity <= 20 percent, except for emissions that have an average opacity in excess of 20 percent for not more than one six-minute period in any 60 consecutive minutes. [LAC 33:III.1311.C]	Review Method 9 Reports	Continuously	7/18/22	5:09 PM	7/18/22	6:00 PM	0.9	While commissioning the liquefaction facility, a power outage occurred, resulting in the flare blowers being inoperable, which resulted in visible emissions from the Warm Flare (EQT 0013) and Cold Flare (EQT 0014) which are air-assisted.	Power was restored to the flare blowers.
EQT 0013 and EQT 0014	Visible Emissions	SRs 52 and 59	Design and operate for no visible emissions, as determined by the methods specified in 40 CFR 60.18(f), except for periods not to exceed a total of 5 minutes during any two consecutive hours. [40 CFR 60.18(c)(1)] Opacity <= 20 percent, except for emissions that have an average opacity in excess of 20 percent for not more than one six-minute period in any 60 consecutive minutes. [LAC 33:III.1311.C]	Review Method 9 Reports	Continuously	7/19/22	12:07 PM	7/19/22	1:00 PM	0.9	While commissioning the liquefaction facility, a power outage occurred, resulting in the flare blowers being inoperable, which resulted in visible emissions from the Warm Flare (EQT 0013) and Cold Flare (EQT 0014) which are air-assisted.	Power was restored to the flare blowers.
EQT 0034	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC 33:III.537]	Records Review	Continuously	7/7/22	1:00 PM	7/7/22	2:00 PM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT1 (EQT 0034) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 60.63 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT1 (EQT 0034) was returned to emissions compliance.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/16/22	8:00 AM	7/16/22	9:00 AM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 46.67 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/18/22	11:00 PM	7/18/22	12:00 AM	1	A process upset occurred due to equipment tripping, resulting in SCCT2 (EQT 0035) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 60.28 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance.
EQT 0035	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/19/22	1:00 PM	7/18/22	4:00 PM	3	While starting up CCCT4 (EQT 0004), the entire plant tripped, resulting in the flame out of SCCT2 (EQT 0035). Estimated NOx max. pounds per hour: 43.9 lb/hr, 72.75 lb/hr, and 78.25 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance.
EQT 0035	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/19/22	2:00 PM	7/18/22	3:00 PM	1	While starting up CCCT4 (EQT 0004), the entire plant tripped, resulting in the flame out of SCCT2 (EQT 0035). Estimated CO max. pounds per hour: 214.09 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT2 (EQT 0035) was returned to emissions compliance.
EQT 0036	VOC and HAPs/TAPs	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/20/22	1:00 PM	7/20/22	8:00 PM	4 (intermittently)	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC max. pounds per hour: 2.02 lb/hr - 2.22 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 29, 2022, SCCT3 (EQT 0036) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.
EQT 0036	VOC	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	7/20/22	1:00 PM	7/20/22	3:00 PM	1	Based on further review of fuel flow rates and high heating values, the VOC emissions exceeded the permit limit. Estimated VOC 3-hour average: 2.13 lb/hr	Calcasieu Pass is reporting these exceedances based on its review of monitoring data. As described by letter dated October 4, 2022 (EDMS Document ID 13511174), as of August 29, 2022, SCCT3 (EQT 0036) is no longer operational. The turbine has been converted to the currently permitted, permanent combined cycle operating mode.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/1/22	9:00 AM	7/1/22	10:00 AM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) going into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 51.41 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/8/22	4:00 PM	7/8/22	5:00 PM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) going into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 51.67 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/18/22	3:00 PM	7/18/22	4:00 PM	1	A process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated CO max. pounds per hour: 70.09 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/18/22	10:00 PM	7/18/22	12:00 AM	2	A process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 50.30 lb/hr - 58.63 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/19/22	3:00 PM	7/19/22	4:00 PM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 55.09 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/19/22	7:00 PM	7/19/22	8:00 PM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 43.72 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/25/22	6:00 AM	7/25/22	7:00 AM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 94.61 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	7/25/22	6:00 AM	7/25/22	7:00 AM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 94.61 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	8/17/22	10:00 AM	8/17/22	11:00 AM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max pounds per hour: 53.45 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	8/26/22	9:00 AM	8/26/22	9:00 PM	8 (intermittently)	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 42.79 lb/hr - 243.08 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	CO	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	8/26/22	1:00 PM	8/26/22	2:00 PM	1	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated CO max. pounds per hour: 120.50 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0036	NOx	SR 120	Comply with the Part 70 General Conditions as set forth in LAC 33:III.535 and Louisiana General Conditions as set forth in LAC 33:III.537. [LAC 33:III.535, LAC33:III.537]	Records Review	Continuously	8/28/22	1:00 PM	8/28/22	3:00 PM	2	While commissioning the liquefaction facility, a process upset occurred due to equipment tripping, resulting in SCCT3 (EQT 0036) dropping into extended lean-lean operating mode. Estimated NOx max. pounds per hour: 63.70 lb/hr and 67.67 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and SCCT3 (EQT 0036) was returned to emissions compliance.
EQT 0051	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	10/27/22	11:00 AM	10/27/22	12:00 PM	1	A process upset occurred due to equipment tripping, resulting in ASCCT1 (EQT 0051) tripping. Estimated NOx max. pounds per hour: 3.31 lb/hr	Before the facility's Energy Management System (EMS) was commissioned, turbine loads had to be manually adjusted and ASCCT1 (EQT 0051) was returned to emissions compliance.



Louisiana DEQ Title V Semiannual Monitoring Form

Deviation Summary Report

Title V Permit Number: 0560-00987-V4

Company Name: VENTURE GLOBAL CALCASIEU PASS, LLC

Facility Name: CALCASIEU PASS PROJECT

AI Number: 194203

Emission Source No./ Identifier	Pollutant(s)	Permit Condition Number	Applicable Compliance Requirement (Include Rule Citation)	Method(s) or Other Means For Determining Compliance Status	Permit Required Monitoring Frequency	Deviation Began		Deviation Ended		Total No. of Hours	Deviation/ Cause(s) of Deviation	Corrective Action(s) Taken
						Date	Time	Date	Time			
EQT 0051	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	11/17/22	1:00 AM	11/17/22	11:00 AM	10	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in ASCCT1 (EQT 0051) tripping and dropping below MECL. Estimated NOx max. pounds per hour: 11.84 lb/hr - 29.29 lb/hr	Operators restored ASCCT1 (EQT 0051) to MECL.
EQT 0051	NOx	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	11/17/22	1:00 AM	11/17/22	11:00 AM	5	High level in cold flare knockout drum tripped all 18 liquefaction trains causing both steam turbines to trip, resulting in ASCCT1 (EQT 0051) tripping and dropping below MECL. Estimated 2-hour avg. NOx pounds per hour: 22.03 lb/hr - 28.95 lb/hr	Operators restored ASCCT1 (EQT 0051) to MECL.
EQT 0051	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/22/22	8:00 AM	12/22/22	3:00 PM	3 (intermittently)	Combustion chamber inner staging valve position feedback failure, resulting in ASCCT1 (EQT 0051) operating in Dry-Low Emission (DLE) Mode. Estimated NOx max. pounds per hour: 2.73 lb/hr - 5.17 lb/hr	Operators implemented corrective measures and ASCCT1 (EQT 0051) was returned to emissions compliance.
EQT 0051	NOx	SR 105	Operate the source in accordance with the terms and conditions of this permit. [LAC 33:III.501.C.4]	Records Review	Continuously	12/23/22	11:00 PM	12/27/22	3:00 AM	77	During the extreme weather conditions (freeze event), facility blackout, and the black start of the facility, ASCCT1 (EQT 0051) tripped multiple times and experienced instrumentation issues. Estimated NOx max. pounds per hour: 2.76 lb/hr - 40.67 lb/hr	Operators restored ASCCT1 (EQT 0051) to MECL as soon as practical after the extreme weather event had passed and instrumentation issues caused by the extreme weather could be resolved.
EQT 0051	NOx	SR 111	Comply with the requirements of PSD-LA-805 (M-4). This permit includes provisions of the Prevention of Significant Deterioration (PSD) review from Permit PSD-LA-805 (M-4).	Records Review	Continuously	12/23/22	11:00 PM	12/27/22	3:00 AM	28 (intermittently)	During the extreme weather conditions (freeze event), facility blackout, and the black start of the facility, ASCCT1 (EQT 0051) tripped multiple times and experienced instrumentation issues. Estimated 2-hour avg. NOx pounds per hour: 15.8 lb/hr - 20.1 lb/hr	Operators restored ASCCT1 (EQT 0051) to MECL as soon as practical after the extreme weather event had passed and instrumentation issues caused by the extreme weather could be resolved.